

PILOT BOARDING ARRANGEMENTS DEFICIENCY REPORT

San Francisco Bar Pilots

Dispatch: (415) 393-0457



Distribute as follows:

Copy to Master of Vessel if possible

ASAP Send to SFBP Port Agent at:

portagent@sfbarpilots.com or fax (415) 393-0456

Vessel: EVER FASHION Master: CAPT. AJAY SHARMA

Date/Time: 6/27/23, 0400 Pilot: M. MANES (UNIT M) Inbound: Outbound:

Conditions: Day: Night: Wind: NW 15 Sea: LT Swell: LOW W Visibility: 6

Transfer Location: (sea/harbor) SEA Embarking: Disembarking:

Vessel Freeboard: 7.0m Vessel Draft: 11.0m Vessel Type: CONTAINER

Ladder Arrangements: Pilot Ladder Only: Combination Ladder: Side Port: Other:

General Arrangement:

Pilot Ladder:

Combination Ladder:

- Insufficient Lighting
- No Responsible Officer
- No Direct Comms w/Bridge
- Not Clear of Discharge
- Not Midships
- Unsafe Deck Access
- Overall Poor Rigging
- Overall Poor Condition

- Poor Condition/Wear
- Not resting on hull
- Rungs not correct material
- Rungs Not Non-Slip
- Rungs Not Horizontal
- Rungs Too Close Together
- Rungs Too Far Apart
- Spreaders Not One Piece
- Spreaders Not Horizontal
- Poor Rigging

- Poor Condition/Wear
- Poor Rigging
- Platform Not Horizontal
- Not Secured to Ship's Side
- Platform Too Low

Man Ropes:

- Poor Condition/Wear
- Incorrect Diameter
- Poor Rigging

See Reverse for IMO-IMPA Required Boarding Arrangements Diagram

REMARKS: (attach photos if possible): _____

STARBOARD SIDE LADDER

Signed _____

Master (if available)

Pilot

1/2 Shall Check The Same And Shall Ensure Rectification (if any) as soon as possible.