



PILOT BOARDING ARRANGEMENTS DEFICIENCY REPORT
San Francisco Bar Pilots
Dispatch: (415) 393-0457

Distribute as follows:
Copy to Master of Vessel if possible

ASAP Send to SFBP Port Agent at:
portagent@sfbarpilots.com or fax (415) 393-0456

Vessel: ELANORA SPRUCE Master: _____
Date/Time: 4/1/2024 Pilot: UNIT 5, MURNET Inbound: Outbound: _____
Conditions: Day: Night: _____ Wind: LIGHT Sea: _____ Swell: LOW Visibility: GOOD
Transfer Location: (sea/harbor) SEA Embarking: Disembarking: _____
Vessel Freeboard: 4.0M Vessel Draft: 37'01" Vessel Type: TANKER
Ladder Arrangements: Pilot Ladder Only: Combination Ladder: _____ Side Port: _____ Other: _____

General Arrangement:

- Insufficient Lighting
- No Responsible Officer
- No Direct Comms w/Bridge
- Not Clear of Discharge
- Not Midships
- Unsafe Deck Access
- Overall Poor Rigging
- Overall Poor Condition

Pilot Ladder:

- Poor Condition/Wear
- Not resting on hull
- Rungs not correct material
- Rungs Not Non-Slip
- Rungs Not Horizontal
- Rungs Too Close Together
- Rungs Too Far Apart
- Spreaders Not One Piece
- Spreaders Not Horizontal
- Poor Rigging

Combination Ladder:

- Poor Condition/Wear
- Poor Rigging
- Platform Not Horizontal
- Not Secured to Ship's Side
- Platform Too Low

Man Ropes:

- Poor Condition/Wear
- Incorrect Diameter
- Poor Rigging

See Reverse for IMO-IMPA Required Boarding Arrangements Diagram

REMARKS: (attach photos if possible): _____

STBD PILOT LADDER MISSING WEDGE ON 2ND
RUNG FROM BOTTOM, STEP UNSECURED AND UNEVEN.

Signed _____

Master (if available)

Pilot/

From: [D11-SMB-SFPortStateControl](#)
To: [Garfinkle, Allen@BOPC](mailto:Garfinkle.Allen@BOPC)
Cc: [D11-SMB-SFPortStateControl](#)
Subject: RE: Elandra Spruce Pilot Ladder deficiency report.
Date: Tuesday, April 2, 2024 12:52:36 PM

Good day,

Well received.

Very Respectfully,

Sector San Francisco
Port State Control
1 Yerba Buena Island, Bldg 26
San Francisco, CA 94130
PSCO: [\(415\) 519-2328](tel:(415)519-2328)
Dispatch: [\(510\) 816-1240](tel:(510)816-1240)

From: Garfinkle, Allen@BOPC <Allen.Garfinkle@bopc.ca.gov>
Sent: Tuesday, April 2, 2024 12:23 PM
To: D11-SMB-SFPortStateControl <D11-SMB-SFPortStateControl@uscg.mil>
Subject: [Non-DoD Source] FW: Elandra Spruce Pilot Ladder deficiency report.

Good day SF Port State Control,

Please see attached Pilot Boarding Equipment Deficiency Report submitted to the Board of Pilot Commissioners for the tanker Elapudra Spruce (I may not have the name correct).

Please acknowledge receipt of this email.

Thank you.

Respectfully,

Allen G.

Allen Garfinkle
Executive Director

Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun
660 Davis Street, San Francisco, California 94111

allen.garfinkle@bopc.ca.gov

Phone: 415-397-2253

Fax: 415-397-9463

From: John Carlier <portagent@sfbarpilots.com>
Sent: Monday, April 1, 2024 12:35 PM
To: Garfinkle, Allen@BOPC <Allen.Garfinkle@bopc.ca.gov>
Subject: Fw: Elandra Spruce Pilot Ladder deficiency report.

EXTERNAL EMAIL. Links/attachments may not be safe.

Allen,

FYI, please see attached Pilot Ladder Deficiency Report.

Best Regards,
John

Captain John Carlier
Port Agent
San Francisco Bar Pilots

From: Dan Murney [REDACTED]
Sent: Monday, April 1, 2024 11:04 AM
To: John Carlier <portagent@sfbarpilots.com>
Cc: Dan Murney [REDACTED]
Subject: Elandra Spruce Pilot Ladder deficiency report.

John,

Please find attached and distribute as necessary.

Regards

Dan Murney
Unit 5

Sent from my Verizon, Samsung Galaxy smartphone
Get [Outlook for Android](#)