

## INVESTIGATION STATUS REPORT

### EVENT

On April 22, 2021, M/V VECCO made contact with the bottom, while down bound on the San Joaquin River in the vicinity of Light 36. Following a sounding of the ship's voids and tanks, it was determined that there was no damage.

### TIMELINE

<b>Investigation Activities</b>	<b>Date</b>	<b>Days Elapsed</b>
Ship Event	4/22/2021	0
Incident Reported to Executive Director	4/22/2021	0
May 2021 Board Meeting	5/27/2021	36
<b>90-day Statutory Deadline</b>	<b>7/20/2021</b>	<b>90</b>

### STATUS

The Incident Review Committee (IRC) has discontinued its investigation based on Board regulation 210(b)(3). In cooperation with the USCG, who confirmed that they have determined that this event was a "bump and go grounding" (as defined in and enclosure to Navigation and Vessel Inspection Circular No. 01-15), the IRC determined there was clearly no pilot error. Based on Board regulation 210(b)(3), the IRC has discontinued the investigation and will report its findings to the Board.

### IRC COMMITTEE MEMBERS

Jennifer Ferrera Schmid, Committee Chair (Public Board Member)  
Allen Garfinkle, Executive Director