

| Part # | Qty | Description | Price | Discount | Total |
|------------|------------|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Parts Subtotal \$8,482.76

Labor

| Description | Technician | Hours | Total |
|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Labor Subtotal \$2,226.00

Job Subtotal \$10,708.76

REPLACE BOTH PORT AND STARBOARD BATTERIES

Description:

Resolution: [REDACTED]

Recommend: [REDACTED]

Parts

| Part # | Qty | Description | Price | Discount | Total |
|------------|------------|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Parts Subtotal \$946.98

Labor

| Description | Technician | Hours | Total |
|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Labor Subtotal \$318.00

Job Subtotal \$1,264.98

REPLACE STEERING HOSES TO THE HELM PUMP

Description:

Parts

| Part # | Qty | Description | Price | Discount | Total |
|------------|------------|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Parts Subtotal \$939.20

Labor

| Description | Technician | Hours | Total |
|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Labor Subtotal \$1,272.00

Job Subtotal \$2,211.20

RESEAL PORT TURBOCHARGER

Description:

Resolution: [REDACTED]

Parts

| Part # | Qty | Description | Price | Discount | Total |
|------------|------------|-------------|------------|------------|------------|
| [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] | [REDACTED] |

Parts Subtotal \$189.26

Labor

